HONDA

URGENT SAFETY RECALL

*On appointment only

A defect exists in certain Takata airbag inflators that can cause excessive pressure within the airbag inflator to rupture the inflator's metallic housing in the event of an airbag deployment during an accident. This can lead to shrapnel penetrating the airbag which may result in serious injury or death.

FREE REPLACEMENT

OF HONDA
AIRBAG INFLATORS

VIN* = Chassis number

YOUR SAFETY IS OUR CONCERN

Models affected:
JAZZ, CITY, CIVIC, CR-V, ACCORD
(2001—2014)

Check if your VIN* is affected on www.honda.co.za/cars/recalls

Call 4389 444 to book an appointment
or Email recall@hondaseychelles.sc

Honda Seychelles | Autoland Complex, Avenue D'Arhoa, Providence, Mahé